

Work Order ID 136264

Friday, August 28, 2015 2:17:42 PM

136264

Page 1

Item ID: D2585

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Latch Clamp

Start Date: 8/28/2015 Start Qty: 15.00

15

Cust Item ID:

Required Date: 8/28/2015 Req'd Qty: 15.00

15

Customer:

Reference:

Approvals: Process Plan: SH/LC Date: 0150901 Tooling: _____ Date: _____Run Start ***NR1***

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D2585	Rev B								
100	FLOW WATER JET	0.00							
100									
Waterjet	Memo	0.00							
FLOW CNC Waterjet	1-Cut as per Dwg D2585 Dwg Rev: <u>B</u> Prog Rev: <u>B</u> 2-Deburr if necessary								
110	QC2- Inspect parts off machine FAI/FAIB	0.00							
110									
QC	Memo	0.00							
Quality Control									
120	QC8- Inspect parts - second check	0.00							
120									
QC	Memo	0.00							
Quality Control									

(18) _____ DC15/09/22

(18) _____ DC15/09/22

(18) _____

DAS
38
9-89
SEP 23 2015

Work Order ID 136264

Friday, August 28, 2015 2:17:42 PM

136264

Page 2

Item ID: D2585

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Latch Clamp

Start Date: 8/28/2015 Start Qty: 15.00

15

Cust Item ID:

Required Date: 8/28/2015 Req'd Qty: 15.00

15

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start ***NR1***

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
130		0.00							
130	Small Fab								
Small Fab	Memo	0.00							
Small Fab	Deburr if necessary								
140		0.00							
140	NC BRAKE								
Brake NC	Memo	0.00							
Brake NC	Form as per Dwg D2585								
150		0.00							
150	QC5- Inspect part completeness to step on W/O								
QC	Memo	0.00							
Quality Control									

N/A

DAS
30
9-89DAS
30
9-89

18

SEP 24 2015

(18)

DAS
38
9-89

SEP 24 2015

Work Order ID 136264

Friday, August 28, 2015 2:17:42 PM

136264

Page 3

Item ID: D2585 Accept ***N900040100*** Setup Start ***NS1***
Revision ID: Stop ***NS2***
Item Name: Latch Clamp
Start Date: 8/28/2015 Start Qty: 15.00 ***15*** Cust Item ID:
Required Date: 8/28/2015 Req'd Qty: 15.00 ***15*** Customer:
Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____ Run Start ***NR1***
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
160	Identify as per dwg & Stock Location: <u>51008</u>	0.00							
160									
Packaging	Memo	0.00							
Packaging									
170	QC21- Final Inspection - Work Order Release	0.00							
170									
QC	Memo	0.02							
Quality Control									

18 DAS 27 9-89
SEP 24 2015
ms SEP 24 2015
JH 20150924

Picklist Print

Friday, August 28, 2015 1:49:39 PM

Page 1

Work Order ID: 136264

136264

Parent Item: D2585

D2585

Parent Item Name: Latch Clamp

Start Date: 8/28/2015

Required Date: 8/28/2015

Start Qty: 15.00

Required Qty: 15.00

Comments: IPP D04.02.16Reformat; Add Receiving StepKJ/RF
IPP C 06.07.21 waterjet EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M304S14GA		Purchased		No		100	sf	119.0000	0.0157	0.247895			

M304S14GA

304SS sheet .080

08/15/09/23

Location

Loc Qty

Loc Code

MAT019

119

M126075

25.5

M129972

93.5

-5

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : _____					





DESIGN BW	DRAWN BY MS	DART AEROSPACE LTD VICTORIA INTERNATIONAL AIRPORT, CANADA	
CHECKED BW	APPROVED BW	DRAWING NO. D2585	REV. B SHEET 1 OF 1
DATE 96:07:11		TITLE MOUNTING CHANNEL	SCALE 1:1
B	97:03:14	ADD FLAT PATTERN	


RELEASED
97/03/14 DS

20150901

54 136264



FLAT PATTERN



MATERIAL: 304/316 SS, 14 GAUGE (0.078)

